ProDOS: Error 900 When Using Apple IIc Sys Utilities Disk (9/95)

```
Revised:        9/19/95
Security:       Everyone
```

ProDOS: Error 900 When Using Apple IIc Sys Utilities Disk (9/95)

```
=====================================================================
```

Article Created: 17 December 1984
Article Reviewed/Updated: 19 September 1995

TOPIC --

I started up my system with the Apple IIc System Utilities Disk. This disk has a
new port configuration saved to it. If I select any menu option then press the
Escape key to return to the main menu, I always drop into the monitor with Error
#900 displayed. How can I get around this?

DISCUSSION ---

The workaround is as follows:

Step 1

Duplicate your Systems Utilities disk: select the main menu option 5. Boot your
system with this new copy.

Step 2

Select main menu option 9 to exit from System Utilities.

Step 3

From the Basic prompt, type in the following:

```
  Load SU,S6
  List 900
```

You will see the listing:

```
  900  Call 768: Poke 216,0: Onerr Goto 930
```

Step 4

Change line 900 to:

```
900  Poke 216,0: Onerr Goto 930: Call 768
```

Step 5

Enter the following commands to unlock the file, save the changes to disk and
relock the file to prevent accidental damage:

```
List 900
```

Step 6

Check once again that line 900 reads properly as in step 4, then type:

```
Unlock SU,S6
Save SU,S6
Lock SU,S6
```


Article Change History:
19 Sep 1995 - Reformatted it to meet current standards

Support Information Services

Apple Technical Communications

Tech Info Library Article Number:899