## Apple IIc (platinum): Mouse Moved from Slot 4 to Slot 7

```
Revised:       10/12/87
Security:      Everyone
```

Apple IIc (platinum): Mouse Moved from Slot 4 to Slot 7

=====================================================================

This article last reviewed: 28 September 1987

When the latest ("platinum") version of the  Apple IIc was released, the
main circuit board was changed to accommodate the new Memory Expansion
Card. The firmware was also changed: the logical location for the mouse was
moved from slot 4 (where the memory card image now resides) to slot 7.

This causes problems when customers run the sample BASIC program in
Appendix A of the AppleMouse II User's Manual. To make the program work
correctly with the newest Apple IIc, change all occurrences of [slot] 4 to
[slot] 7.

Tech Info Library Article Number:790