DOS 3.3: RENUMBER and the FRE(0) command

```
Revised:        11/20/84
Security:       Everyone
```

DOS 3.3: RENUMBER and the FRE(0) command

==

RENUMBER doesn't always reset the variable pointers when it returns to
Applesoft, causing the Apple to hang or drop into the monitor when the PRINT
FRE(0) command is used. To check the amount of free memory left after a
RENUMBER operation, CLEAR before using PRINT FRE(0).

Apple Tech Notes

Tech Info Library Article Number:576