AppleWorks 2.1: Apple IIc Plus Disk Drive Labelling Correction

Revised: 11/2/88
Security: Everyone

AppleWorks 2.1: Apple IIc Plus Disk Drive Labelling Correction

==

This article last reviewed: 12 October 1988

The Apple IIc Plus has an internal 3.5" disk drive, which the older
Apple IIc system didn't have. AppleWorks has a menu item under "Add Files"
for changing current disk. When chosen, this menu item displays a list of
available disks.

On an Apple IIc Plus with the internal 3.5" drive, AppleWorks 2.0 displays
the following list of drives:

1. Built-in disk
2. Ext. disk IIc
3. Disk 3.5 #1
4. ProDOS directory

    NOTE: AppleWorks 2.0 uses the following associations between
           slot/drive and the labels as displayed above:

1. Built-in disk   Slot 6, Drive 1
2. Ext. disk IIc   Slot 6, Drive 2
3. Disk 3.5 #1   Slot 5, Drive 1
4. ProDOS directory   (the pathname typed in response to this selection)

When running on a Apple IIc Plus:

1. The built-in disk is actually the first external 5.25" drive.
2. The "Ext. disk IIc" is the second external 5.25" drive.
3. The "Disk 3.5 #1" label is the internal 3.5" drive mounted in the
    Apple IIc Plus.

These labels are correct for the older Apple IIc systems, but the labels do
not correctly identify the internal disk drive for the Apple IIc Plus.
Claris has revised AppleWorks 2.0 to correct the associations. Contact
Claris for information about the AppleWorks 2.1 update.

For more information, search under: Claris

Tech Info Library Article Number:3347